
Installation and Communication

Engineering Drawing



Installation Guidelines

- Fixed side: locate with the Ø24 mm flange pitch diameter; fasten with M2 screws.

- Load side: connect the load via the Ø9 mm flange pitch diameter; ensure coaxial alignment.

- Cable exit: side exit; allow sufficient cable bend clearance.

Communication Pinout

No.	Pin
1	VCC
2	GND
3	485_N
4	485_P