






Screws must not be excessively long.  
Otherwise, motor damage may occur.



| GENERAL TOLERANCES PER ISO 2768-m |               |                 |                  |                   |
|-----------------------------------|---------------|-----------------|------------------|-------------------|
| $\leq 6$                          | $> 6 \leq 30$ | $> 30 \leq 120$ | $> 120 \leq 400$ | $> 400 \leq 2000$ |
| $\pm 0.1$                         | $\pm 0.2$     | $\pm 0.3$       | $\pm 0.5$        | $\pm 1.0$         |

| SCALE |  | 4310-10SHSINSTALLATION DRAWING |  |
|-------|--|--------------------------------|--|
| 1 : 1 |  |                                |  |