







(8108-6)

Unmarked tolerance segment (x)				
x≤6	6<x≤30	30<x≤120	120<x≤400	400<x≤2000
±0.1	±0.2	±0.3	±0.5	±1.0

GIM8108-6 installation diagram	
Proportion	
Weight/kg	