


INSTALLATION DRAWING



MOTOR CHARACTERISTIC CURVE

— Inputdc Current — Efficiency — Output Power — Output Torque)

